



Green Bank Machine Shop

MS Order #	Work Order	Qty	Description	Priority Level	RCD	ECD	Estimated Hours	Status	Originator
		7	S-Band Feed TF & Rings & WR SN22-SN29		7/10/2010				
		9	Ku-Band OMT Lot 5 (SN26-SN34)		9/25/2010			8/27/2010	
		4	Ku-Band Feed Lot 4 (SN14-SN17)		10/13/2010			Shipped 10/11/10	
		2	VLBA C-Band Feeds Prototypes (SN1-SN2)		1/17/2010	2/14/2011			
		4	VLBA C-Band Feeds (SN3-SN6)		4/1/2011				
		3	VLBA C-Band Feeds (SN7-SN9)		7/18/2011				
		4	Ku-Band Feed Lot 5 (SN18-SN21)		10/15/2011				
		3	VLBA C-Band Feeds (SN10-SN12)		12/20/2011				
		4	Ku-Band Feed Lot 6 (SN22-SN25)		3/15/2012				

Charlottesville NTC

MS Order #	Work Order	Qty	Description	Priority Level	RCD	ECD	Estimated Hours	Status	Originator
CV	Ku-Band 20101006 (Circ2Sq WO&Plt SN 6,13,17).pdf	3	Wash Out and Plate Ku S2C		11/25/2010			RX SN13 (11/04/10) RX SN6 (???)	
CV	X-Band 20101019 (CircToSqEform SN13,14,17).pdf	3	Eform X C2S		12/26/2010			RX All 12/13/10	
CV	Ku-Band 20101026 (Circ Sq eformSN 9,14,26).pdf	3	Eform Ku S2C		2/5/2011			RX All	
CV	Ku-Band 20101026 (45 Twist electroform SN 19, 35, 40).pdf	3	Eform Ku 45T		12/5/2010	2/10/2011		RX All 20110126	
CV	Ku-Band 20101101 (Circ2Sq WO & Plt SN 11 & 12).pdf	2	Wash Out and Plate Ku S2C		3/20/2011	3/20/2011		RX All 20110126	
CV	X-Band 20101118 (CircToSqEform SN12,15,16).pdf	3	Eform X C2S		3/29/2010			RX All (12/13/20)	
CV	Ku-Band 20101203 (45 Twist WO&Plate SN 22,23,34,38,39).pdf	5	Wash Out and Plate Ku 45T		1/1/2011	1/24/2011		RX (38,28,23) 20110126	
CV	X-Band 20101220 (CircToSqWO&Plt SN13,14,17).pdf	3	Wash Out and Plate X-Band S2C		2/27/2011	2/27/2011		RX 14,17 20110126	
CV	Ku-Band 20101220 (Circ Sq WO & Plt SN 09).pdf	1	Washout and Plate Ku S2C		4/20/2011	4/20/2011		RX All 20110126	
CV	Ku-Band 20101220 (CaltechSq Circ Wo&plate SN 6 & 14).pdf	2	Washout and Plate Ku S2C		1/10/2011	1/25/2011		RX All 20110126	