















		1	List	of	u-v Da	ita				
Source=	J0121+11	Freq=	8	.43	4858511	Sort	TB	1	RR	
Vis #	IAT	Ant	Su	Fq	U(klam)	V(klam)	W(klam)	Amp	Phas W	řt.
2191	0/22:35:08.2	22 5- (5 1	0	94220	23776	100371	0.614	-16 1	.0000
3971	0/22:43:43.3	34 5- 6	5 1	0	97659	24517	96844	0.508	-13 1	.0000
6431	0/23:07:05.1	15 5- 6	5 1	0	106307	26661	86632	0.154	17 1	.0000
6611	0/23:07:14.9	8 5- 6	5 1	0	106364	26677	86557	0.152	17 1	.0000
6791	0/23:07:24.8	31 5- 6	5 1	0	106421	26692	86483	0.150	18 1	.0000
6971	0/23:07:34.0	34 5- 6	5 1	0	106477	26708	86408	0.148	19 1	.0000
7151	0/23:07:44.4	17 5- 6	5 1	0	106534	26724	86333	0.146	19 1	.0000
7331	0/23:07:54.3	30 5- 6	5 1	0	106591	26739	86259	0.144	20 1	.0000
7511	0/23:15:06.8	34 5- 6	5 1	0	109027	27438	82930	0.101	74 1	.0000
7691	0/23:15:16.0	37 5- 6	5 1	0	109081	27454	82854	0.101	75 1	.0000
7871	0/23:15:26.8	50 5- 6	5 1	0	109135	27470	82777	0.102	77 1	.0000
8051	0/23:15:36.3	33 5- 6	5 1	0	109189	27486	82701	0.102	78 1	.0000
8231	0/23:15:46.1	6 5- 6	5 1	0	109243	27502	82624	0.103	79 1	.0000
8411	0/23:15:55.9	9 5- 6	5 1	0	109297	27518	82547	0.104	81 1	.0000
9701	0/23:31:02.3	36 5- 6	5 1	0	114020	29035	75322	0.260	134 1	.0000
9791	0/23:31:06.3	29 5- 6	5 1	0	114040	29042	75290	0.261	134 1	.0000
10301	0/23:31:29.8	38 5- 6	5 1	0	114156	29082	75098	0.266	134 1	.0000
10861	0/23:39:02.0	08 5- 6	5 1	0	116320	29863	71379	0.348	139 1	.0000
10951	0/23:39:06.0)1 5- (5 1	0	116339	29870	71346	0.348	139 1	.0000
11171	0/23:39:15.8	34 5- 6	5 1	0	116384	29887	71264	0.350	139 1	.0000



























































New Mexico Tec



